



Safety Kleen Systems, Inc.
Fargo Service Center Fact Sheet
North Dakota Department of Health
Division of Waste Management

Telephone: 701.328.5166
Telecopy: 701.328.5200
Web site: www.ndhealth.gov/wm
Revision: 03.2008

Facility Name: Safety Kleen Systems, Inc., Fargo Service Center

State/EPA ID#: NDD000716738

Address and Location:
1537 First Avenue South
Fargo, ND 58103

State Contact: Ivana Striebel
Phone: 701-328-5166
Fax: 701-328-5200
Email: icstriebel@nd.gov

Lead Agency:
North Dakota Department of Health, Division of Waste Management

Setting and Operations History:
The Safety-Kleen Systems, Inc. Fargo Service Center Facility, located at 1537 First Avenue South, Fargo, North Dakota, operates hazardous waste management units, which include a container storage area and a tank storage system to store hazardous waste solvents. All wastes are eventually shipped off-site to approved facilities for final treatment or disposal. This facility is an accumulation center for many materials generated by conditionally exempt small quantity generators and small quantity generators of hazardous waste. Most of the waste is amenable to reclamation and is ultimately shipped to recycling facilities or contract reclaimers and returned to customers as product. Safety-Kleen Systems' customers are primarily automotive repair, industrial maintenance, and dry cleaning services. This facility began operations on September 1, 1978.

Regulatory Instrument (Permit/Order):
Instrument: Storage Permit
Issued By: North Dakota Department of Health
Date: Permit renewed on February 15, 2008 and is in effect until February 15, 2013

Regulated Units:
Safety-Kleen Systems operates hazardous waste units which include a container storage area and a tank storage area. The container storage area is not to exceed 2,400 gallons and has secondary containment of 470 gallons. The storage tank is not to exceed 85% of 12,000 gallon capacity and has secondary containment of 31,551 gallons.

Waste Generation:
The container storage area may hold: spent immersion cleaner, dry cleaning waste, aqueous parts cleaner waste, photographic imaging waste, and dumpster sediment from the spent immersion cleaner. The tank storage area may hold spent parts cleaning solvent and small amounts of the aqueous parts cleaner waste.

RCRA Compliance Status:
No current issues with compliance.

Potential for Releases:

No areas of concern have been identified.

Corrective Action Status and Stabilization Activities:

N/A

Community Involvement:

N/A

Major Up-Coming Activities:

None

Problems/Issues:

None